TO: Rosedale-Rio Bravo Water Storage District Board of Directors

Agenda Item 7.a.i

FROM: Dan W. Bartel

DATE: April 9, 2024


RE: Onyx Ranch Operations Report

Discussion:

Staff has:

- Continued operation of conveyance facilities
- Irrigation activities resumed March 11 after precipitation subsided.
- USGS verified the South Fork station on March 5.
- Staff did not stream gage during the month due to high flows.
- Staff completed ditch cleaning activities on the Smith Ditch.
- Staff demolished old shop in preparation for replacement.
- Staff began construction of the slab for the new shop building.

South Fork flows downstream of Bloomfield averaged 176 cfs plus calculated accretions of 8 cfs, for a total average flow of about 184 cfs.



△ Median daily statistic (97 years) ** Measured discharge
─ Discharge





